BRUHAT BANGALORE MAHANAGARA PALIKE

No. EE(H)AE/TS/ 10 /12-13

Office of the Executive Engineer,
Hebbal Division, Queen's Road,
Bangalore, Dated: 02-05-2012

TECHNICAL SANCTION MEMO

Sub: Estimate for the work of : Repairs to footapth in HIG Layout in W-18

Ref: Administratively Sanctioned Vide No. EE/H/AS/ 08 /12-13
Date: 30-04-2012

* * * *

In pursuance to the Administrative sanction accorded by Executive Engineer (Hebbal) exercising the powers delegated by the Commissioner in the proceedings B12(1)/PR-394/2011-12 dated: 13.3.2012. Technical Sanction for Rs. 2.00 Lakhs is accorded and registered in E.E. (H) technical Register page No: 80 Sl. No. 10 .

The following points shall be attended by the Asst., Executive Engineer (Hebbal / ~~JC Nagar~~) Sub-Division:-

1. Approval of Competent Authority is to be obtained before execution of any deviation excess quantity.
2. For non-schedule items, sealed quotations to be invited & got approved by the competent Authority before execution if any.
3. The Assistant Executive Engineer, (Hebbal/ JC Nagar) Sub Division, should get the work done as per specifications & Submit bills along with the quality control reports
4. Expenditure of the work is chargeable to **P-1771 POW for the year 2011-12**

Executive Engineer,
Hebbal Division,
Bruhat Bangalore Mahanagara Palike.